

## INDUSTRY:

Transportation

## LOCATION:

Caribbean

## SCOPE OF WORK:

Full floor replacement & internal floating roof repair of 45'D X 48'H tank.

- Door sheet access
- Hydraulic jacking tank lift
- Full floor plate removal & replacement
- New nozzles, manway and repad installation
- Repair of HMT internal floating roof
- Re-installation of door sheet as per API 653
- Hydro test tank as per API 653

## QUALITY:

- Repair as per API 653
- 100% UT in lieu of RT as per API 650
- 100% visual and MPI of all welds
- Full floor vacuum box and corner box X3 as per CT&V policy

## SCHEDULE:

Completed on schedule.

## CONTRACT TYPE:

Lump Sum

## SPECIALTY ITEMS:

- Tank lift with hydraulic jacks
- Repair internal aluminum HMT floating roof

## SAFETY:

0 Near Misses  
0 First Aids  
0 Recordables

## REFERENCE CONTACT:

Available Upon Request

## Project Number: MB367

